



Bush Fire Ltd

**Unit 14
Watermill Business Centre
Edison Road
Enfield
Middlesex
EN3 7XF
Email.Info@bushfire.co.uk**



DRY RISING MAIN
CERTIFICATE of INSPECTION and TEST
Carried out in Accordance with B.S. 9990 2015

Certificate No. 20218

Service Address
Fire and Security Consultancy Ltd
Noble House
4 Queensway , Redhill
Surrey RH1 1TX

**RECEPTION RISER
VISUAL INSPECTION VISIT**

ITEM INSPECTED	DETAILS	PASS	FAIL
Valves		✓	
Pipework		✓	
Instantaneous Seals		✓	
Straps and Padlocks	Queen master	✓	
Signs		✓	
Cabinet Locks	Queen master	✓	
Blank Caps & Chains		✓	

LOCATION OF EQUIPMENT

Inlet	Front of building right of reception
Low level drain point	At inlet also, G level leg
Highest Outlet	Approximate Height 90 Feet 6 Floors
Is System Operational (Ready for use)	

HYDRAULIC TEST

Water Pressure at Inlet 12 Bar (174psi)			
Pressure at Outlet 8.5 Bar	Pass	✓	Fail
Pipework/Valves at Pressure	Pass	✓	Fail
System Drained Down Yes via inlet also G level valve			

Description of any defects

Inspection Date 26/2/2021
For Bush Fire:



Bush Fire Ltd

**Unit 14
Watermill business Centre
Edison Road
Enfield
Middlesex
EN3 7XF
Tel: 0208443 4016
Email: Info@bushfire.co.uk**



FS606249



DRY RISING MAIN
CERTIFICATE of INSPECTION and TEST
Carried out in Accordance with B.S. 9990 2015

Certificate No. 20217

Service Address
Fire and Security Consultancy Ltd
Noble House
4 Queensway
Redhill
Surrey RH1 1TX

**FIRE ESCAPE RISER
VISUAL INSPECTION VISIT**

ITEM INSPECTED	DETAILS	PASS	FAIL
Valves		✓	
Pipework		✓	
Instantaneous Seals		✓	
Straps and Padlocks	Queen master	✓	
Signs		✓	
Cabinet Locks	Queen master	✓	
Blank Caps & Chains		✓	

LOCATION OF EQUIPMENT

Inlet	Front of building by pedestrian crossing
Low level drain point	At inlet also G level leg
Highest Outlet	Approximate Height 90 Feet 6 Floors
Is System Operational (Ready for use)	

HYDRAULIC TEST

Water Pressure at Inlet 12 Bar (174psi)			
Pressure at Outlet 8.5 Bar	Pass	✓	Fail
Pipework/Valves at Pressure	Pass	✓	Fail
System Drained Down Yes via inlet <i>yes</i>			

Description of any defects

Inspection Date *26/12/2021*
For Bush Fire: *[Signature]*